

March 11, 1982

With the compliments of,

BERT SIEGEL

TO: CHARLES PAUL ATARI:

Dear Skip;

Per Joe Robbins discussion with Marty Bromley
I enclose herewith the sample PCB of our ALI BABA.
I also enclose a copy of the instructions for
the harness wiring diagram. If you have any
questions, please call me.

Kindest regards,


BERTRAM L. SIEGEL

430 N. Maple Dr., #104

Beverly Hills, Calif. 90210

Phone: (213) 550-7608

Telex: 686164 Segamus, BVHL

Segasa

Apartado 16117

MADRID-SPAIN

Teléf. 232 66 40

Cable: Segastar

BUT - 6
RIGHT - 1
LEFT - 2
UP - 3
DOWN - 4
GND - 8

Player 1

R - 1 5
L - 1 6
U - 1 7
D - 1 8
Fire - 9

2
R 13
L 14
U 16
D 15
F 17

ST 1 - 19

ST 2 - 20

CRAD - 4

INSTRUCTION FOR ALTEADA HARNESS WIRING DIAGRAM

PARTS FACE
NAME OF SIGNAL

SOLDERING FACE
NAME OF SIGNAL

GND	1	A	GND	DC
GND	2	B	GND	DC
GND	3	C	GND	DC
GND	4	D	SGND OUT (SP)	Grey Brown/Black
R/B "12 V	5	E	"12V	
	6	F	1P UP	Grey/Blue
Grey/Pk 1P BARRIER BUTTON	7	H	2P UP	Green/Yellow
	8	J		
Red "5V	9	K	"5V	
Grey 1P DOWN	10	L		
White/Green 2P DOWN	11	M		
	12	N	2P START	White
Blue COIN SW	13	P	1P START	Blue
	14	R	1P RIGHT	Yellow

~~15-16~~

Red ^{RED} 15 ^S 1P LEFT ORANGE

Yellow ^{RED} 16 T BLUE Purple

GRN 2P LEFT 17 U GREEN Gen

White/Grey 2P BARRIER BUTTON 18 V SYNC White/Pk

REGS I.M (ICM)